


VIP-192 Firmware Upgrade Procedure

Please set the network topology as below:



Upgrade Procedure:

Step1→ Please check the current version is v01.00.04 or newer, and then please continues the step 2.

Step2→ To save the firmware file into your computer (e.g. **C : **)

Step3→ Open a DOS prompt and direct to **C: ** and then type the command
tftp -i **XXX.XXX.XXX.XXX** put **filename**

Note:

- ♦ **XXX.XXX.XXX.XXX** is the IP address of the VIP-192
- ♦ **filename** is the file name of the firmware (e.g. FW-VIP192_010212.img)

```
C:\>tftp -i 192.168.0.100 put FW-VIP192_010212.img
Transfer successful: 5167076 bytes in 67 seconds, 77120 bytes/s
C:\>
```

Step4→ After transfer the data successful, then the VIP-192 will start to upgrade.

Note:

It will take around 8 minute for the download process. And then it will reboot and restore the default setting automatically.

Step5: After finished upgrading, you can re-login VIP-192's Web UI to check the firmware version is correct which you had upgraded.

Notes:

1. This firmware release is only compatible with versions 01.00.04 and newer. If your firmware is older, please contact with your vender and do not attempt to upgrade.
2. The firmware download method is to execute the MS-DOS and type the command "**C : \>tftp -i XXX.XXX.XXX.XXX put filename**".
XXX.XXX.XXX.XXX is the IP address of the VIP-192 and 'filename' is the file name of the firmware (e.g. FW-VIP192_010212.img).
3. To check your current firmware version, press [Menu] -- > [Information] then page 3/3. (e.g. " version: 01.02.08")
4. Connecting the power adaptor while downloading will prevent the system from crashing due to the battery running out.
5. Please close to the AP while downloading. If the wireless signal is higher, the transmission will be faster.
6. If possible, disable the encryption to make the transmission faster.
7. Restore to the default setting manually by dialing "**255*000**" and [offhook] in the standby mode.
8. If errors occurred while updating file causing the product to not boot up correctly, please contact with your vendor or directly contact with PLANET technical support.



PLANET Technology Corporation

11F, No. 96, Min Chuan Road, Hsin Tien, Taipei, Taiwan, R.O.C.

Tel: 886-2-2219-9518 Fax: 886-2-2219-9528

Email: sales@planet.com.tw Web site: <http://www.planet.com.tw>

VoIP Gateway: vip.planet.com.tw

Planet reserves the right to change specifications without prior notice.
All brand names and trademarks are property of their respective owners.
Copyright (c) 2006 PLANET Technology Corp. All rights reserved