## **Speed Dome Internet Camera Installation Guide**



Step 1:
Take out Speed dome IP Cam from carton



Step 2:
Use screw drive to take off the decoration ring





Step 3:
Use screw driver to take off the screw of embedded mount









## Step 4:

Follow the anti-clockwise direction to take away the Speed dome body from the embedded mount. Take off the safety hook


Note: "Safety hook" is to avoid the IP cam falling down to the floor



Step 5:
Cut a hole as following in the false ceiling



Step 6:
Push the embedded mount to the hope, and drive the 3 screws until the embedded ring fits the ceiling tightly and solidly



Step 7:

Make sure the safety hook is connected, and follow the clockwise direction to close the Speed dome body to the embedded ring



Step 8:
Use screw drive to drive the screw within Speed dome body and embedded ring



Step 8:
Use screw drive to fix the decoration ring. Installation procedure finished